


HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3YF-1RF

PROPELLER S/N EE4469B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position SINGLE ENGINE

Propeller Model PHC-C3YF-1RF

Propeller S/N _____

Blade Design F8068

Blade S/N's

No. 1 J87462

No. 2 J87467

No. 3 J87466

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. A2295-1P

PITCH RANGE

High/Feather 36.2^{HIGH}/36.4 - ~~12.2-12.4~~

Start Lock _____

Low 12.2-12.4


Reverse N/A



Aircraft Manufacturer BEECHCRAFT

Aircraft Model V35B

S/N D-9761

Registration N1156T


Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
5/16/03			<p align="center"><u>Propeller log</u> Aerospace Systems & Technologies Inc. 3213 Arnold Ave. Salina, KS 67401 Tel: (785) 493-0946 N1156T <u>May 16, 2003</u> <u>Make: Beechcraft</u> <u>Model: V35B</u> <u>Prop TTSN: 0.0</u> <u>S/N: D-9761</u> <u>Tach: 0707.5</u></p> <p>Installed Hartzell propeller and spinner assembly per STC#SA01548CH. FAA Form 337 on filed this date. Added TKS boots to the blades and a slinger ring to the spinner bulkhead per STC#SA2239CE. Dynamically balanced the propeller to <u>0.05</u> in/sec. Dynamic Systems Solutions Micro-vib balancing system used. With respect to the work performed above this propeller is considered to be airworthy. THIS AIRCRAFT IS NOT APPROVED FOR FLIGHT INTO KNOWN ICING CONDITIONS AT ANY TIME</p> <p align="center"> Timothy J. Werner AP5108055861A</p>

NOLAND-DECOTO FLYING SERVICE YAKIMA, WASHINGTON	McCormick Air Center LLC 2108 W. Washington Ave Yakima, WA 98903
DATE <u>7-30-03</u> TIME <u>742.1 TA-14</u>	Date <u>10/8/04</u> TT <u>136.8</u> Tach <u>944.3</u>
I certify this aircraft/engine/ <u>propeller</u> has been inspected in accordance with an <u>annual</u> 100 hour inspection and was determined to be in an air-worthy condition. ELT Due <u>---</u>	I certify this aircraft/engine/ <u>propeller</u> has been inspected in accordance with an annual/100 hr. inspection and was determined to be in an air worthy condition, ELT Due <u>---</u>
AD Notes thru <u>2003-20F</u>	AD Notes thru <u>2004-20F</u> <u>AP 2042149 TA</u>
Authorized Signature 	Authorized Signature 
FAA Approved Repair Station No <u>GGNA-269E</u>	

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<p>McCormick Air Center 2108 W. Washington Ave. Yakima, WA. CRS KB6R659N 12/4/2006 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 288.9 Tach: 996.4 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD's checked through 2006-24F. Refer to AD Compliance Record & W/O 2339 dated 11/6/06. I certify this propeller was found airworthy and is approved for return to service.</p> <p><i>Doug Brown</i> CRS KB6R659N</p>
				<p>McCormick Air Center 2108 W. Washington Ave. Yakima, WA. CRS KB6R659N 12/1/2007 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 327.1 Tach: 1034.6 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD's checked through 2007-24F. Refer to AD Compliance Record & W/O 2805 dated 11/16/07. I certify this propeller was found airworthy and is approved for return to service.</p> <p><i>Doug Brown</i> CRS KB6R659N</p>

				<p>McCormick Air Center 2108 W. Washington Ave. Yakima, WA. CRS KB6R659N 12/18/08 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 354.2 Tach: 1061.7 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD2007-26-09 found not applicable to blade SN's installed. AD's checked through 2008-25F. Refer to AD Compliance Record & W/O 3298 dated 12/8/08. I certify this propeller was found airworthy and is approved for return to service.</p> <p><i>Doug Brown</i> CRS KB6R659N</p>
				<p>McCormick Air Center 2108 W. Washington Ave. Yakima, WA. CRS KB6R659N 1/28/2010 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 370.7 Tach: 1078.2 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD2007-26-09 found not applicable to blade S/N's installed. AD's checked through 2010-13-02F. Refer to AD Compliance Record & W/O 3706 dated 1/28/2010. I certify this propeller was found airworthy and is approved for return to service.</p> <p><i>J. DeL...</i> CRS KB6R659N</p>

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				<p align="center">McCormick Aircraft Maintenance 2108 W. Washington Ave. Yakima, WA.</p> <p>5/18/2011 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 375.3 Tach: 1082.8 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD's checked through 2011-10F. Refer to AD Compliance Record & W/O 6082. I certify this propeller was found airworthy and is approved for return to service.</p> <p align="right"><i>[Signature]</i> AP3371085A</p>
				<p align="center">McCormick Aircraft Maintenance 2108 W. Washington Ave. Yakima, WA.</p> <p>07/06/2012 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 383.7 Tach: 1091.2 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD's checked through 07/05/2012. Refer to AD Compliance Record & W/O 6280. I certify this propeller was found airworthy and is approved for return to service.</p> <p align="right">J. Stuhley AP3425882IA <i>[Signature]</i></p>
				<p align="center">McCormick Aircraft Maintenance 2108 W. Washington Ave. Yakima, WA.</p> <p>08/13/2013 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 394.3 Tach: 1101.8 Inspected propeller for an annual inspection per 14CFR 43 appendix D. AD's checked through 08/13/2013. Refer to AD Compliance Record & W/O 6461. I certify this propeller was found airworthy and is approved for return to service.</p> <p align="right">J. Stuhley AP3425882IA <i>[Signature]</i></p>



				<p align="center">McCormick Aircraft Maintenance 2108 W. Washington Ave. Yakima, WA.</p> <p>10/14/2014 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 399.3 Tach: 1106.8 Inspected propeller for a 100 hour inspection per 14CFR 43 appendix D. AD's checked through 10/13/2014. Refer to AD Compliance Record & W/O 6672. I certify this propeller was found airworthy and is approved for return to service.</p> <p align="right"><i>[Signature]</i> G. Fortier A/P2704311</p>
				<p align="center">McCormick Aircraft Maintenance 2108 W. Washington Ave. Yakima, WA.</p> <p>10/14/2014 Hartzell PHC-C3YF-1 SN: EE4469B N1156T TT: 399.3 Tach: 1106.8 Inspected propeller for an Annual inspection per 14CFR 43 appendix D. AD's checked through 10/13/2014. Refer to AD Compliance Record & W/O 6672. I certify this propeller was found airworthy and is approved for return to service.</p> <p align="right"><i>[Signature]</i> A+P 22329645A</p>